


## Structure notes – 103 W Liberty





Google Street View September 2017



Historic resources survey photo, 1992

## Summary:

- Built ca. 1930. Sometime probably after 1990 a 12-ft addition was built across the back to house the washing stations of the salon, along with a carport. The original roof framing and much of the original roof remain in place under the carport roof (refer to photos).
- Other than the rear addition the most significant changes are the porch columns and ADA ramp.
- On the interior some of the doorways and wall openings have changed to accommodate salon functions, but the walls appear to be in their original locations.
- Windows, siding and front door all appear original and need stripping/painting/moderate repair. Have not investigated/tested for lead paint.
- Have not checked for structural/water/insect damage but have not noticed anything obvious (except on carport).
- State of HVAC and insulation is unknown. No kitchen cabinets or appliances remain.





Front porch with ADA extension and plywood floor. Original brick wings by steps.



West side



West side



Carport has water damage. Original roof visible underneath. Addition starts where siding changes.




East side windows need repair.



Back (addition)



East side where original house meets addition



Wall between living and dining rooms has been altered